



**RE7L2SK**

**#2 Solid Copper Conductor  
to  
#7 & Larger Reinforcing Bar**

## Description

---

#2 Solid Copper Conductor to #7 & Larger Reinforcing Bar  
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1