

**RS7L2SB**

**#2 Solid Copper Conductor
to
#7 & Larger Reinforcing Bar**

Description

#2 Solid Copper Conductor to #7 & Larger Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1