



**RE31/0B**

**1/0 Stranded Copper Conductor  
to  
#3 Reinforcing Bar**

**Description**

---

1/0 Stranded Copper Conductor to #3 Reinforcing Bar  
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1