



**RE66B**

**#6 Stranded Copper Conductor  
to  
#6 Reinforcing Bar**

**Description**

---

#6 Stranded Copper Conductor to #6 Reinforcing Bar  
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1