



**RE64B**

**#4 Stranded Copper Conductor  
to  
#6 Reinforcing Bar**

**Description**

---

#4 Stranded Copper Conductor to #6 Reinforcing Bar  
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1