



PT26B

**#6 Stranded Copper Conductor
to
#2 Stranded Copper Conductor**

Description

#6 Stranded Copper Conductor to #2 Stranded Copper Conductor
Parallel Thru Splice of Horizontal Cables, Tap Conductor Over Run

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1